Coll #

00684.003093.3

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

KAZUSHIGE SAKURAI, ET AL.)

Appln. No.: 10/656,377

Filed: September 8, 2003

For: IMAGE FORMING APPARATUS AND

CARTRIDGE DETACHABLY : MOUNTABLE THERETO)

Examiner: H. Tran

Group Art Unit: 2852

Patent No.: 6,807,382 B1

Issued: October 19, 2004

February 8, 2005

Certificate FEB 1 6 2005

PATENT

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

of Correction

Attention: CERTIFICATE OF CORRECTION BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

02/10/2005 HGUTEMA1 00000136 6807382

01 FC:1811

100.00 OP

Accompanying this letter is a check for \$100.00 to cover the statutory fee for issuing a Certificate of Correction to correct errors of the patentees. Any deficiency should be charged, or any overpayment credited, to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for this purpose.

Patentees' attorney, Gary M. Jacobs, may be reached by telephone in our Washington, D.C. office at (202) 530-1010 or by facsimile at (202) 530-1055. All correspondence should be directed to our address given below.

Respectfully submitted,

Jack/S. Cubert

Attorney for Patentees Registration No. 24,245

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2200

JSC/llp

DC_MAIN 191473v1

CERTIFICATE OF CORRECTION

PATENT NO. :

6,807,382 B1

DATED

October 19, 2004

INVENTOR(S) :

KAZUSHIGE SAKURAI, ET AL.

Page 1 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

IN THE DRAWINGS

Sheet 19, FIG. 20, "ASSEMBRY" should read -- ASSEMBLY --. Sheet 31, FIG. 32, "ASSEMBRY" should read -- ASSEMBLY--.

COLUMN 1

Line 19, "means" should read --means.--.

Line 33, "cas" should read --case--.

Line 49, "The" should read --the--.

Line 56, "Image" should read --image--.

COLUMN 3

Line 55, "Present" should read --present--.

COLUMN 4

Line 25, "Image" should read --image--.

Line 38, "whilst" should read --which--.

Line 47, "holds;" should read --holds:--.

COLUMN 5

Line 24, "by" (first occurrence) should read --with--.

Line 56, "surf ace" should read --surface--.

Line 58, "anti" should read --and--.

Line 62, "vd" should read -- Vd--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) JSC/Tip DC_MAIN 191474

PATENT NO. 6,807,382 B1

No. of add'l. copies @ 30¢ per page

FEB 1 7 2005,

CERTIFICATE OF CORRECTION

PATENT NO.

6,807,382 B1

DATED

October 19, 2004

INVENTOR(S) :

KAZUSHIGE SAKURAI, ET AL.

Page 2 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6

Line 15, "in" should read --is--. Line 49, "ion" should read --on--.

COLUMN 7

Line 59, "teems" should read --terms--.

COLUMN 8

Line 2, "In" should read --in--.

Line 13, "Lives" should read --lives--.

COLUMN 10

Line 1, "contr l" should read --control--. Line 7, "data-D" should read --data D--.

COLUMN 11

Line 33, "in" (second occurrence) should read --is--.

COLUMN 12

Line 5, "value a" should read --value α --.

Line 63, "In" should read --in--.

Line 66, "In" should read --in--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

PATENT NO. 6,807,382 B1

Form PTO 1050 (Rev. 3-82)

(Form#30) JSC/Ilp DC_MAIN 191474

FEB 1 7 2005

CERTIFICATE OF CORRECTION

PATENT NO. :

6,807,382 B1

DATED

October 19, 2004

INVENTOR(S) :

KAZUSHIGE SAKURAI, ET AL.

Page 3 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 13

Line 41, "Switched." should read --switched.--.

COLUMN 14

Line 5, "6Z" should read --62--.

Line 28, "h" should read $--\beta$ --.

Line 29, "y" should read -- γ --.

Line 48, "H" (first occurrence) should read -- M--.

Line 67, "DC-voltage" should read --DC voltage--.

COLUMN 15

Line 3, "hither" should read --higher--.

Line 61, "In" should read --in--.

COLUMN 18

Line 27, "he" should read --the--.

COLUMN 20

Line 11, "assumably;" should read --assembly, --.

Line 37, "In" should read --is--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) JSC/Ilp DC_MAIN 191474

PATENT NO. 6,807,382 B1

No. of add'l. copies @ 30¢ per page

<u></u> ≪

CERTIFICATE OF CORRECTION

PATENT NO.

6,807,382 B1

DATED

October 19, 2004

INVENTOR(S) :

KAZUSHIGE SAKURAI, ET AL.

Page 4 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 21

Line 35, "Image" should read -- image--.

COLUMN 22

Line 7, "a" should read $--\alpha$ --.

Line 49, "It" should read --it--.

COLUMN 23

Line 16, "a" should read -- α --.

Line 20, "of" should read --to--.

Line 25, "currant" should read --current--.

Line 37, "email" should read --small--.

Line 42, "Individual" should read --individual--.

COLUMN 24

Line 18, "a" should read $--\alpha$ --.

Line 22, "of" should read --to--

Line 54, ":is" should read --is--.

Line 58, "war" should read --was--.

Line 61, "are" should read --is--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,807,382 B1

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

FEB 1 7 2005

No. of add'l. copies

@ 30¢ per page

CERTIFICATE OF CORRECTION

PATENT NO. :

6,807,382 B1

DATED

October 19, 2004

INVENTOR(S) :

KAZUSHIGE SAKURAI, ET AL.

Page 5 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 25

Line 13, "In" should read --in--.

Line 17, "v" should read --a--.

Line 25, "continues" should read --continues.--.

COLUMN 26

Line 35, "Get" should read --set--.

Line 63, "development-bias" should read --development bias--.

COLUMN 27

Line 48, "of" should read --to--.

COLUMN 28

Line 51, "as" should read --at--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

_~

PATENT NO. 6,807,382 B1

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) JSC/lip DC_MAIN 191474

FEB 1 7 2005





In re Patent of:)	
	:	Examiner: H. Tran
KAZUSHIGE SAKURAI, ET AL.)	
	:	Group Art Unit: 2852
Appln. No.: 10/656,377)	-
••	:	Patent No.: 6,807,382 B1
Filed: September 8, 2003)	
•	:	Issued: October 19, 2004
For: IMAGE FORMING APPARATUS AND)	·
CARTRIDGE DETACHABLY	:	February 8, 2005
MOUNTABLE THERETO)	<u>-</u>
	•	

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Attention: CERTIFICATE OF CORRECTION BRANCH

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for issuing a Certificate of Correction to correct errors of the patentees. Any deficiency should be charged, or any overpayment credited, to Deposit Account No. 06-1205. A duplicate of this paper is enclosed for this purpose.

Patentees' attorney, Gary M. Jacobs, may be reached by telephone in our Washington, D.C. office at (202) 530-1010 or by facsimile at (202) 530-1055. All correspondence should be directed to our address given below.

Respectfully submitted,

Jack/S. Cubert

Attorney for Patentees Registration No. 24,245

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2200

JSC/llp

DC_MAIN 191473v1

CERTIFICATE OF CORRECTION

PATENT NO.

6,807,382 B1

DATED

October 19, 2004

INVENTOR(S) :

KAZUSHIGE SAKURAI, ET AL.

Page 1 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

IN THE DRAWINGS

Sheet 19, FIG. 20, "ASSEMBRY" should read --ASSEMBLY--. Sheet 31, FIG. 32, "ASSEMBRY" should read --ASSEMBLY--.

COLUMN 1

Line 19, "means" should read --means.--.

Line 33, "cas" should read --case--.

Line 49, "The" should read --the--.

Line 56, "Image" should read --image--.

COLUMN 3

Line 55, "Present" should read --present--.

COLUMN 4

Line 25, "Image" should read --image--.

Line 38, "whilst" should read --which--.

Line 47, "holds;" should read --holds:--.

COLUMN 5

Line 24, "by" (first occurrence) should read --with--.

Line 56, "surf ace" should read --surface--.

Line 58, "anti" should read -- and --.

Line 62, "vd" should read -- Vd--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) ISC/ID DC MAIN 191474

PATENT NO. <u>6,807,382 B1</u>

No. of add'l. copies @ 30¢ per page

 \Rightarrow ____

FEB 1 7 2005

CERTIFICATE OF CORRECTION

PATENT NO.

6,807,382 B1

DATED

October 19, 2004

INVENTOR(S) :

KAZUSHIGE SAKURAI, ET AL.

Page 2 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 6

Line 15, "in" should read --is--.

Line 49, "ion" should read --on--.

COLUMN 7

Line 59, "teems" should read --terms--.

COLUMN 8

Line 2, "In" should read --in--.

Line 13, "Lives" should read --lives--.

COLUMN 10

Line 1, "contr l" should read --control--.

Line 7, "data-D" should read --data D--.

COLUMN 11

Line 33, "in" (second occurrence) should read --is--.

COLUMN 12

Line 5, "value a" should read --value α --.

Line 63, "In" should read --in--.

Line 66, "In" should read --in--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30) JSC/Ilp DC_MAIN 191474

PATENT NO. 6,807,382 B1

No. of add'l. copies @ 30¢ per page

 \Rightarrow -

TEB 1 7 2005

CERTIFICATE OF CORRECTION

PATENT NO.

6,807,382 B1

DATED

October 19, 2004

INVENTOR(S) :

KAZUSHIGE SAKURAI, ET AL.

Page 3 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 13

Line 41, "Switched." should read --switched.--.

COLUMN 14

Line 5, "6Z" should read --62--.

Line 28, "h" should read $--\beta$ --.

Line 29, "y" should read -- γ --.

Line 48, "H" (first occurrence) should read --M--.

Line 67, "DC-voltage" should read --DC voltage--.

COLUMN 15

Line 3, "hither" should read --higher--.

Line 61, "In" should read --in--.

COLUMN 18

Line 27, "he" should read --the--.

COLUMN 20

Line 11, "assumably;" should read --assembly,--.

Line 37, "In" should read --is--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)
(Form#30) JSC/IIp DC_MAIN 191474

PATENT NO. 6,807,382 B1

No. of add'l. ∞pies @ 30¢ per page

⇒ _

FEB 1 7 2005,

CERTIFICATE OF CORRECTION

PATENT NO.

6,807,382 B1

DATED

October 19, 2004

INVENTOR(S) :

KAZUSHIGE SAKURAI, ET AL.

Page 4 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 21

Line 35, "Image" should read --image--.

COLUMN 22

Line 7, "a" should read $--\alpha$ --.

Line 49, "It" should read --it--.

COLUMN 23

Line 16, "a" should read $--\alpha$ --.

Line 20, "of" should read --to--.

Line 25, "currant" should read --current--.

Line 37, "email" should read --small--.

Line 42, "Individual" should read --individual--.

COLUMN 24

Line 18, "a" should read $--\alpha$ --.

Line 22, "of" should read --to--

Line 54, ":is" should read --is--.

Line 58, "war" should read --was--.

Line 61, "are" should read --is--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30) JSC/llp DC_MAIN 191474 PATENT NO. 6,807,382 B1

No. of add'l. copies @ 30¢ per page

__>

CERTIFICATE OF CORRECTION

PATENT NO. :

6,807,382 B1

DATED

October 19, 2004

INVENTOR(S) :

KAZUSHIGE SAKURAI, ET AL.

Page 5 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 25

Line 13, "In" should read --in--.

Line 17, "v" should read --a--.

Line 25, "continues" should read --continues.--.

COLUMN 26

Line 35, "Get" should read --set--.

Line 63, "development-bias" should read --development bias--.

COLUMN 27

Line 48, "of" should read --to--.

COLUMN 28

Line 51, "as" should read --at--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. 6,807,382 B1

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)
(Form#30) JSC/lip DC_MAIN 191474